

Location

Gateway 12 Business Park is located 3 miles to the South West of Gloucester, adjacent to the A38 dual carriageway and just two miles from Junction 12 of the M5.

Additionally, the A38 provides dual carriageway access to the Gloucester Ring Road and the South West Bypass.

Major occupiers within the local vicinity include the Gloucester Constabulary HQ, DPD, Amazon and Parcel Force.

A38

<u> S</u>

0.5 of a mile west

M5



Junction 12 2 miles north

Gloucester



3 miles

Nearby Population









Accommodation

Description

The property comprises a superb detached warehouse building located on a self-contained plot.

It is constructed on a steel portal frame with a mix of brick and profile sheet clad elevations. The frame provides an internal working height of approximately 8 metres to the underside of the frame haunch.

Ground and first floor office and amenity accommodation is provided to a high standard including perimeter trunking, suspended ceilings and LED lighting.

Loading is provided by three level access loading doors from the concrete yard, which has a maximum depth of approximately 35 metres. Separate car parking is provided.


Services

We are advised that all main services are connected to the premises. We confirm that we have not tested any of the service installations and any occupier must satisfy themselves independently as to the state and condition of such items. Areas are approximate Gross Internal Floor Areas.

Area	Sq ft	Sq m
Warehouse	32,518	3,020.98
Offices	5,566	517.09
First floor and offices	5,566	517.09
TOTAL	43,650	4,055.16













Planning | Rates | EPC | Terms

Planning

Gateway 12 Business Park originally had planning consent for warehouse, general/light industrial and offices (B8, B2 and B1). The property has been used for warehouse use (B8).

Business Rates

The property requires a separate assessment for businesss rates. Interested parties should make their own enquiries to the billing authority to ascertain the exact rates payable as a change in occupation may trigger an adjustment of the ratings assessment.. www.voa.gov.uk.

Energy Performance Certificate

The EPC Rating is B43 and the full certificate can be provided on request.

Code for Leasing

For the latest RICS advice on commercial property leasing, please consult the RICS Real Estate Code for Leasing 2020

Terms

The property is available on a new full repairing lease with terms to be negotiated.

Legal Costs

Each party is to be responsible for their own legal costs.

References/Rental Deposits

Financial and accountancy references may be sought from any prospective tenant prior to agreement. Prospective tenants may be required to provide a rental deposit subject to the landlord's discretion.

VAT

Under the Finance Acts 1989 and 1997, VAT may be levied on the rent. We recommend that the prospective tenants establish the VAT implications before entering into any agreement.

AML

A successful tenant will be required to provide relevant information to satisfy the AML requirements when Heads of Terms are agreed.

Viewing Arrangements

For further information or to arrange an inspection, please contact the agents:



Alder King Property Consultants

Brunswick House Gloucester Business Partk Gloucester GL3 4AA

www.alderking.com

AK Ref: AR/LG/N96944

Date: June 2022

Subject to Contract



Adrian Rowley 01452 623290 07771 874 175 arowley@alderking.com

Important Notice

Alder King LLP is a Limited Liability Partnership registered in England and Wales. No OC306796. Registered Office: Pembroke House, 15 Pembroke Road, Clifton, Bristol BS8 3BA. A list of all Members is available at the Registered Office.

1. Money Laundering Regulations 2017

As part of our obligations under the UK Money Laundering Regulations, Alder King LLP requires any purchaser or tenant to provide information and documentation to satisfy our legal obligations.

2. Misrepresentation Act 1967

This marketing brochure is for guidance only and does not form part of any offer or contract and must not be relied upon as statements or representations of fact.

3. Control of Asbestos Regulations 2012 (CAR 2012)

It is the responsibility of the owner or tenant of the property, and anyone else who has control over it and/or responsibility for maintaining it, to comply with the regulations. The detection of asbestos and asbestos-related compounds is beyond the scope of Alder King and accordingly we recommend you obtain advice from a specialist source.